

SAFETY DATA SHEET

TYRE REPAIR

Issued on 11/15/2010 - Rel. # 1 on 01/25/2016

1 / 11

In conformity to Regulation (EU) 2015/830

SECTION1. Identification of the substance/mixture and of the company/undertaking

1.1. Product identifier

Product code: ALT34 TYRE REPAIR

1.2. Relevant identified uses of the substance or mixture and uses advised against

Tyre inflates & repair

Sectors of use:

Private households (= general public = consumers)[SU21]

Product category:

Automotive Care Products

Uses advised against

Do not use for purposes other than those listed

1.3. Details of the supplier of the safety data sheet

Beal UK, Texas St, Leeds, LS27 0HG – 0113 253 8888

Email: sales@beal.org.uk – Web: www.beal.org.uk

1.4. Emergency telephone number

CAV "Osp. Pediatrico Bambino Gesù" - Piazza Sant'Onofrio, 4 Roma 06-68593726

Az. Osp. Univ. Foggia - V.le Luigi Pinto, 1 Foggia 0881-732326

Az. Osp. "A. Cardarelli" - Via A. Cardarelli, 9 Napoli 081-7472870

CAV Policlinico "Umberto I" - V.le del Policlinico, 155 Roma 06-49978000

CAV Policlinico "A. Gemelli" - Largo Agostino Gemelli, 8 Roma 06-3054343

Az. Osp. "Careggi" U.O. Tossicologia Medica - Largo Brambilla, 3 Firenze 055-7947819

CAV Centro Nazionale di Informazione Tossicologica - Via Salvatore Maugeri, 10 Pavia 0382-24444

Osp. Niguarda Ca' Granda - Piazza Ospedale Maggiore, 3 Milano 02-66101029

Azienda Ospedaliera Papa Giovanni XXII - Piazza OMS, 1 Bergamo 800-883300

Super Help srl +39 347 4650120 (supporto tecnico - dal lunedì al venerdì 8:00-12:00 e 13:30-17:30)

SECTION2. Hazards identification

2.1. Classification of the substance or mixture

2.1.1 Classification according to Regulation (EC) No 1272/2008:

Pictograms:

GHS02, GHS07

Hazard Class and Category Code(s):

Flam. Aerosol 1, Skin Irrit. 2

Hazard statement Code(s):

H222 - Extremely flammable aerosol

H229 - Pressurised container: May burst if heated

H315 - Causes skin irritation

Aerosol that ignites easily even at low temperatures, fire risk

If brought into contact with the skin, the product causes significant inflammation with erythema, scabs, or edema

The repeated inhalation of vapors can cause drowsiness and giddiness.

